


## Dripshield, NEMA 4X

- Clean top of enclosure with solvent to remove dirt and oil residues.
- Locate dripshield position per dimensions below. Mark and drill mounting holes in enclosure with a 13/64 drill bit. Mounting holes are predrilled in the dripshield.
- Apply sealing compound to mounting flange of dripshield and around each mounting hole. Position dripshield and secure with stainless screws with o-rings and stainless nuts.



This accessory maintains UL/CSA Type 12,4,4X when installed per these instructions.

This accessory is covered by UL file E61997 and CSA file LR42186.