


ERICO® CADWELD®

Ground Plate and Cable to Steel Surface



Prior to making a connection, read and follow the full instruction sheet:
 IPP = Grounding applications
 IPP & IPRNS = Rail properties
 shipped with ERICO CADWELD mold and special instructions below.

1. Place mold firmly against flat steel surface.
2. Insert ground plate until flange area comes in contact with back of mold. Back off the ground plate 0.06inch [2 mm].
3. Position cable in mold as shown, in contact with ground plate stud.

WARNING:

1. ERICO products shall be installed and used only as indicated in ERICO product instruction sheets and training materials. Instruction sheets are available at www.erico.com and from your ERICO customer service representative.
2. ERICO products must never be used for a purpose other than the purpose for which they were designed or in a manner that exceeds specified load ratings.
3. All instructions must be completely followed to ensure proper and safe installation and performance.
4. Improper installation, misuse, misapplication or other failure to completely follow ERICO's instructions and warnings may cause product malfunction, property damage, serious bodily injury and death.

SAFETY INSTRUCTIONS:

All governing codes and regulations and those required by the job site must be observed. Always use appropriate safety equipment such as eye protection, hard hat, and gloves as appropriate to the application.



CADDY, CADWELD, CRITEC, ERICO, ERIFLEX, ERITECH, and LENTON are registered trademarks of ERICO International Corporation.