## CERTIFICATE OF COMPLIANCE

E482010 **Certificate Number** E482010 - 20230807 **Report Reference Issue Date** 2023-OCTOBER-19 HOFFMAN ENCLOSURES INC Issued to: 2100 Hoffman Way Anoka, MN 55303-1738 United States ENVIRONMENTAL-RATED ACCESSORIES FOR This certificate confirms that **ENCLOSURES** representative samples of See Addendum Page for Model(s) Have been evaluated by UL in accordance with the Standard(s) indicated on this Certificate. UL 508A Standard For Industrial Control Panels Standard(s) for Safety: UL 508 Standard For Industrial Control Equipment CSA C22.2 No. 14-18 Industrial Control Equipment Additional Information: See UL Product iQ<sup>®</sup> at https://ig.ulprospector.com for additional information.

This Certificate of Compliance indicates that representative samples of the product described in the certification report have met the requirements for UL certification. It does not provide authorization to apply the UL Mark. Only the Authorization Page that references the Follow-Up Services Procedure for ongoing surveillance provides authorization to apply the UL Mark.

Only those products bearing the UL Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.

Look for the UL Certification Mark on the product.

Sa Mall

Bruce Mahrenholz, Conformity Assessment Director



Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact UL Customer Service at <a href="http://ul.com/aboutul/locations/">http://ul.com/aboutul/locations/</a>

## CERTIFICATE OF COMPLIANCE

Certificate Number Report Reference Issue Date E482010 E482010 – 20230807 2023-OCTOBER-19

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements.

Exhaust filter kits and filter fan kits – Models, HN0416413, HN0416413R, HN0426413, HN0426413R, HN0426413R, HN0426413R, HN0516513, HN0516513R, HN0516513R, HN0526513, HN0524513, HN0524513R, HN0816513, HN0816513R, HN0826513, HN0826513R, HN0826513R, HN0826513R, HN0926513, HN0926513R, HN0926513R, HN0926513R, HN0924513, HN0924513, HN0924513R, HN1216513R, HN1226513R, HN1226523R, HN0400403, HN0500503, HN0800503, HN0900503, HN1200503, HN0416414, HN0416414R, HN0426414, HN0426414R, HN0426414R, HN0426414R, HN0526514R, HN0526514R, HN0526514R, HN0526514R, HN0524514R, HN0926514R, HN1226524R, HN1216514R, HN1226514, HN1226524R, HN1226524R, HN1226524R, HN0400404, HN0500504, HN0800504, HN0900504, HN1200504.

Barnally

Bruce Mahrenholz, Conformity Assessment Director



Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact UL Customer Service at <a href="http://ul.com/aboutul/locations/">http://ul.com/aboutul/locations/</a>